Amendments to the Specification

Please replace the paragraph beginning on page 2, lines 17-22, with the following rewritten paragraph:

In said JP-A-H05-254532, since said bottom-reinforcing sections are provided in the circumferential wall portion (that is, a heal-heel portion of the bottle, where the bottom is connected to the body), only the heel portion is reinforced I the bottom. A portion exerting grounding function is not reinforced at all. Hence, there is a problem in the past that stable "seat" function cannot be obtained by JP-A-H05-254532.

Please replace the Abstract with the attached amended Abstract.